SRK105.SLDDRW 10/18/2010 4:28 PM

REV.	DESCRIPTION	ECN	DATE	BY
Α	NEW DRAWING	C-4261	10/23/2006	TEG
В	ADDED ITEMS # 22,23	C-5484	5/23/2008	DRB
С	PART NO. WERE WC NO.	7044	5/22/2009	EFR
D	ADDED -01 REPAIR KIT	7426	3/8/2010	TLK
Е	E ADDED ITEM 14/15 TO SRK105, RMVD KING PIN #4 FROM SRK105-01		10/11/2010	TLK







SERVICE REPAIR KIT SRK105-01			20K KINGPIN REPAIR KIT MERITOR
ITEM	PART NO.	QTY	DESCRIPTION
1	143622-0006	2	BUSHING 20K INC KNUCKLE
2	3208N1028	2	GASKET KINGPIN CAP 20K
3	S258P2	6	CAPSCREW 20K
4	A1228D1382	1	THRUST BEARING 20K
5	2203N3004	1	SHIM .005 (AS REQD) 20K
6	2203M3003	1	SHIM .010 (AS REQD) 20K
7	2203A2835	1	SHIM .015 (AS REQD) 20K
8	2203B2836	1	SHIM .030 (AS REQD) 20K
9	1229E1669P	6	WASHER FLAT 20K
10	A1205Y1429	2	SEAL OIL 20K
11	7X114	1	DRAW KEY
12	1227Z780	1	NUT KEY
13	1898R720	2	GREESE FITTINGS 1/8" 20K
14	1199M3237	2	KING PIN CAP 20K





